

MiVoice Connect

Release 19.3

Version 22.22.6100.0

Release Notes

May 2024



About

Release Note (RN) is intended for Customer Service and Installation Personnel involved in the installation and maintenance of MiVoice Connect 19.3.

NOTICE

The information contained in this document is believed to be accurate in all respects but is not warranted by Mitel Networks Corporation. The information is subjected to change without notice and should not be construed in any way as a commitment by Mitel or any of its affiliates or subsidiaries. Mitel and its affiliates and subsidiaries assume no responsibility for any errors or omissions in this document. Revisions of this document or new editions may be issued to incorporate changes.

MiVoice Connect
Release 19.3
July 2022

®,™ Trademark of Mitel Networks Corporation
© Copyright 2022, Mitel Networks Corporation
All rights reserved

Table of Contents

Overview	3
Product Enhancements and Functional Changes.....	4
Software Release History	5
Software and Firmware Versions.....	6
Release 19.3 Build Dates	6
PBX and Client Versions.....	6
PBX Switch Versions	7
Phone Versions	7
Application Requirements	9
Accessing the Latest version of MiVoice Connect Software	13
Documentation	13
Training	14
Important Links	14
Installation and Upgrade Notes	14
Resolved Issues	18
Known Issues	21
Known Product Limitations.....	22

Overview

Release Notes contain the most current information on the MiVoice Connect 19.3 Release and the supported solution lineup.

The release note includes the following:

- Software Enhancements
- Functional Changes
- Installation and Upgrade information
- Fixes for Customer reported issues
- Known Issues

Important: Functional changes to Connect Client in Release 19.3

In MiVoice Connect 19.3, The Connect Client has been upgraded to the latest Chromium version. As a result of this update, the Outlook voicemail add-in has been deprecated and it is no longer possible to play voicemail messages from Outlook mail. Two solutions exist to work-around this problem:

- Use Connect Client to play Voicemails
- Send the Voicemail as attachment and play as a media file. This option can be enabled from Director.

The Outlook Contacts Plugin and Outlook UCB Plugin are supported with Single Sign On logins to the Connect Client. These features will **NOT** work with basic Connect Client PBX authentication. If you require this functionality, disable the Automatic Client updates before upgrading to 19.3

Microsoft Internet Explorer Notice: Discontinuation of Support Next Release

MiVoice Connect 19.3 will be the last release to support Internet Explorer browser as Microsoft stopped supporting on June 15, 2022.

Product Enhancements and Functional Changes

MiVoice Connect PBX 22.22.6100.0
<p>Teleworker Support for 6900 IP Phone Series</p> <p>Beginning with MiVoice Connect Release 19.3 and SIP phone firmware Version 6.2.0.1018, 6900-Series (6920, 6930, and 6940) phones have teleworker support with Ingate SBC SIParator version 6.4.</p> <p>For more information on configuration and deployment of solution, please review the <i>MiVoice Connect Installing and Configuring MiVoice Connect with InGate Server Guide</i></p> <p>Security Enhancements: Enable/Disable TLS 1.0/1.1</p> <p>Beginning with Release 19.3, users can use the Enable TLS1.0 and TLS 1.1 option in the Additional Parameters page in Connect Director to enable/disable TLS 1.0 and TLS 1.1 in all MiVoice Connect components.</p> <p>For more information, see the <i>Configuring Other System Parameters</i> section in the <i>MiVoice Connect System Administration Guide</i>.</p> <p>Security Provisioning: Enable/Disable FTP Anonymous server</p> <p>Users can use the “Enable FTP Anonymous server” option in the additional Parameters page in Connect Director to enable/disable TLS 1.0 and 1.1 in all the MiVoice Connect.</p> <p>MySQL Update</p> <p>In release 19.3, MySQL version is upgraded from 5.7.29 to 5.7.37 Community edition.</p> <p>Red Sky Organizational ID Field Update</p> <p>Beginning with Release 19.3, the Organization ID field in the RedSky portal is updated to the HELD Company ID.</p> <p>For more information, see the following sections in the <i>MiVoice Connect RAY BAUM’S General Overview and Solution Deployment Guide for RedSky</i>:</p> <ul style="list-style-type: none"> • RedSky • Horizon Mobility Setup - RedSky Portal • Connect Client Integration with RedSky

Connect 6900 Phone Series Features
<p>6900 Teleworker Support via Ingate SIParator:</p> <p>Beginning with MiVoice Connect Release 19.3 and phone firmware Version 6.2.0.1018, 6900-Series (6910, 6920, 6930, and 6940) phones have teleworker support with Ingate SIParator running software version 6.4.</p> <p>For more information, see the <i>MiVoice Connect Ingate SIParator as Teleworker Gateway for MiVoice Connect 6900 Series Configuration Guide</i></p>

MiVoice Connect Client 214.100.3131.0
Chromium Update for Connect Client <p>the Connect Client was updated to support the latest Chromium. In addition to a refreshed User Interface, the updated Connect Client supports Mac OS 12 “Monterrey”.</p> <ul style="list-style-type: none"> Before upgrading, please review the <i>Connect Client User Guide</i> and review section <i>Differences between Old and New Client Interface</i> before upgrading to 19.3 as some functionality has changed.

Connect IP400 Phone Series Features
Bug Fixes only

Software Release History

Software Load	Release Name	Release Date
22.22.6100.0	Release 19.3	July 2022
22.20.2300.0	Release 19.2 SP3	Dec 2021
22.20.1300.0	Release 19.2 SP2	Nov 2021
22.18.4600.0	Release 19.2 SP1 (revised)	Aug 2021
22.18.4000.0	Release 19.2 SP1	Jun 2021
22.13.4800.0	Release 19.2	Nov 2020
22.11.9300.0	Release 19.1 – SP2	April 2020
22.11.4900.0	Release 19.1 – SP1	Feb 2020
22.10.7600.0	Release 19.1	Sept 2019
21.90.9743.0	R1807 – Onsite- SP2	July 2019
21.90.9738.0	R1807 – Onsite- SP1	Feb 2019
21.90.4127.0	R1807 – Onsite	Oct 2018
21.88.3753.0	R1804 – Onsite – SP1	Sept 2018
21.88.3731.0	R1804 – Onsite	Jun 2018
21.87.9727.0	R1803 – Onsite	May 2018

21.87.3629.0	R1801 - Onsite	Feb 2018
21.86.1828.0	R1711 – Onsite	Jan 2018
21.84.5543.0	R1707 - Onsite – SP2	Dec 2017
21.84.5535.0	R1707 - Onsite – SP1	Oct 2017
21.84.5523.0	R1707 – Onsite	Sep 2017
21.82.9645.0	R1704 – Onsite – SP2	Aug 2017
21.82.9630.0	R1704 - Onsite – SP1	Jul 2017
21.82.9623.0	R1704 – Onsite	Jun 2017

Software and Firmware Versions

Release 19.3 Build Dates

PBX Build:	June 27, 2022
6900 Series firmware:	June 27, 2022
IP400 series firmware:	June 27, 2022
Client Software:	June 27, 2022
Telephony for Microsoft software version:	June 27, 2022

PBX and Client Versions

PBX Engineering Build number:	22.22.6100.0
Distributed Voice Server (DVS) version number:	22.22.6100.0
Connect Client Software version:	214.100.3131.0
Telephony for Microsoft software version:	22.22.6100.0

PBX Switch Versions

Switch Version Firmware	22.22.6100.0
Switch (SG Kilauea ½ width) Boot ROM Version	1.1.3.29
V-Switch Boot ROM Version	1.1.3.29
Switch ST24A Boot ROM Version:	8.2.241.0
Switch ST50A.ST100A Boot ROM Version:	U-Boot 2011.03 V11
Switch ST100DA Boot ROM Version:	U-Boot 2011.03 V11
Switch ST1D/ST2D Boot ROM Version	U-Boot 2011.03 V11
Switch ST200/ST500 Boot ROM Version	U-Boot 2011.03 V11
Switch ST24A/ST48A Boot ROM Version	U-Boot 2011.03 V11

Phone Versions

IP-110 Firmware Version	S03.9.13
IP-115 Firmware Version	S01.3.9.13
IP-212K Firmware Version	S12.3.9.13
IP-230 Firmware Version	SEV.3.9.13
IP-230g Firmware Version	SEVG.3.9.13
IP-265 Firmware Version	S36.3.9.13
IP-530 Firmware Version	S2.3.9.13
IP-560 Firmware Version	S6.3.9.13
IP-560g Firmware Version	S6G.3.9.13
IP-565g Firmware Version	S6C.3.9.13
IP-655g application Firmware Version	SWE.4.4.14

Release Notes

IP655g Boot ROM Firmware Version	SWE.4.4.10
BB-24 Firmware Version	SBB.3.9.13
IP8000 Firmware Version	4.5.2(9)
IP930D (DECT Phone)	SD1.0.0.63
IP930D Phone Boot Version	SD1.0.0.56
IP930D Phone Application Version	v.63
IP930D Phone handset firmware	v.95
IP930D Base Station Firmware	v.95
IP930D Phone Repeater Version	v.39
IP8430M Phone (Multi-Cell DECT phone)	v410_b3
IP8630M Phone (Multi-Cell DECT phone)	v410_b3
IP8830M Phone (Multi-Cell DECT phone)	v410_b3
IP8860M Phone Base Station Firmware	v410_b3
IP4024M Repeater Firmware	v410_b3
IP420 Firmware	804.2205.1300.0
IP420G Firmware Version	804.2205.1300.0
IP480 Firmware Version	804.2205.1300.0
IP480G Firmware Version	804.2205.1300.0
IP485G Firmware Version	804.2205.1300.0
IPBB424 Firmware Version	6.2.0.1018
IP-6910 Firmware Version	6.2.0.1018
IP-6920 Firmware Version	6.2.0.1018
IP-6930 Firmware Version	6.2.0.1018

Release Notes

IP-6940 Firmware Version	6.2.0.1018
IP-6970 (SIP) Firmware Version	5.1.1.7032
Mitel SIP-DECT Base stations	Release 8.3 SP1
Mitel SIP-DECT Handsets:612d,622d and 632d	v7.2.5

Application Requirements

Mitel Main and Distributed Servers (Standalone, VMware and Hyper-V) *	<ul style="list-style-type: none"> Windows Server 2019 (Standard or Datacenter) Windows Server 2016 (Standard or Datacenter) Windows Server 2012 R2 (Standard or Datacenter Editions only, 64 bit)
	<ul style="list-style-type: none"> VMware 6.0,6.5, 6.7 and 7.0 – Support for HQ, WDVS, LDVS, vSwitch, Virtual Service Appliance, vMMR and vEGW
	<ul style="list-style-type: none"> Microsoft Hyper-V Gen 1 and 2 on Microsoft Windows 2012 R2 support for HQ, WDVS, LDVS, vSwitch and VSA Microsoft Hyper-V Gen 1 on Microsoft Windows 2016 – HQ, WDVS, LDVS, vSwitch, vEGW, vMMR and vSA Microsoft Hyper-V Gen 1 and on Microsoft Windows 2019 – HQ, WDVS, LDVS, vSwitch, vEGW, vMMR and vSA
Mitel supplied SBE / Distributed Servers	<ul style="list-style-type: none"> UC25 – Windows Server 2012 (SBE Only) UC30 – Windows Server 2016 / 2019 UC75 – Windows Server 2016 Standard
Mitel Connect Client for Windows	<ul style="list-style-type: none"> Microsoft Windows 8 Professional & Enterprise, 32 & 64-bit Microsoft Windows 8.1 Professional and Enterprise, 32 and 64-bit Microsoft Windows 10 Professional and Enterprise, 32 and 64-bit WTS (30 Clients) Citrix XenApp 7.15 LTSR Citrix XenApp 7.6 LTSR (30 Clients) Citrix XenDesktop Support
Mitel Connect Client for macOS X	<ul style="list-style-type: none"> Apple OS X 10.11 “El Capitan” Apple macOS <ul style="list-style-type: none"> 10.12 “Sierra” 10.13 “High Sierra”

	<ul style="list-style-type: none"> ○ 10.14 “Mojave” ○ 10.15 “Catalina” ○ 11.6 “Big Sur” ○ 12.2 “Monterey” ● SAFARI 15.0 (16612.1.29.41.4)
VMware	<p>Support for Mitel HQ WDVS, LDVS, vSwitch, vSA and vMMR, vEGW and Connect Contact Center is as follows (this includes support for High Availability and vMotion):</p> <ul style="list-style-type: none"> ● VMware ESXi 6.0, 6.5, 6.7 and 7.0 ● VMXNet3 Virtual adapter (not the E1000) <p>The following two VMware features are not supported:</p> <ol style="list-style-type: none"> 1. Fault tolerance is not supported. 2. Snapshots not supported except during service shutdown periods. These can consume significant CPU and memory resources impacting system operation. <p>Note: Unless specifically in Mitel documentation or Mitel App Notes, third party solutions are not supported on Mitel virtual machines. Please check with the third-party solution vendor for their compatibility in a virtual environment and their level of support with virtual machines. Also consult the Planning and Installation Guide and Connect Migration Guide before deploying.</p> <p><i>Please refer to Main and Distributed Voice systems for supported operating systems.</i></p>
Hyper-V	<ul style="list-style-type: none"> ● Microsoft Hyper-V Gen 1 and 2 on Microsoft Windows 2012 R2 – Support for HQ, WDVS, LDVS, vSwitch, vSA and vMMR ● Microsoft Hyper-V Gen 1 on Microsoft Windows 2016 – HQ Server, WDVS, LDVS, vSwitch, vEGW, vMMR and vSA. ● Microsoft Hyper-V 2019 on Microsoft Windows 2019 Server – HQ Server, WDVS, LDVS, vSwitch, vEGW, vMMR and vSA. <p>*Note: Hyper-V Replica or Snapshots can only be performed during service shutdown periods.</p> <p>The following Hyper-V features are not supported:</p> <ol style="list-style-type: none"> 1. Double Take <p>Note: Unless specifically in Mitel documentation or Mitel App Notes, third party solutions are not supported</p>

	on Mitel virtual machines. Please check with the third-party solution vendor for their compatibility in a virtual environment and their level of support with virtual machines. Also consult the Planning and Installation Guide and Connect Migration Guide for deployment.
Internet Browsers for Director	<ul style="list-style-type: none"> • Internet Explorer 21H1 Build 19043.176 • MS Edge 103.0.1264.37 • Firefox 101.0.1 • Google Chrome 103.0.5060.66 • Safari 15.0
Mitel 6900 Headsets	<p>Tested 3rd Party Headsets:</p> <ul style="list-style-type: none"> • USB wired Headset • Plantronics Blackwire C725 (Firmware v.135) • BT Headsets • Plantronics Voyager Legend (Firmware v107) • Jabra Pro 935 (Firmware v1.4.6) • Jabra Evolve 65 UC (Firmware 1.5.8) • Jabra Motion UC (Firmware 3.72) • Jabra Pro 9460 (Firmware 1.4.6) • Analog • Plantronics CS540 (with APS-11 EHS accessory) • Jabra 2300 Duo (with LINK 14201-10 accessory cable) • GN Netcom 2100 series <p>Important Notes: Please see headset vendor sites for compatibility of headsets and required accessory cables with Mitel 6900 SIP phones. It is very likely analog EHS headsets integrated with the IP400 phone require a different EHS cable to function correctly.</p>
Mitel 6900 MobileLink Supported Mobile phone OS	<ul style="list-style-type: none"> • iOS, 13.x, 14.x, 15.x • Android 10.x, 11.x, 12.x
Mitel Softphone Headsets	<p>Softphone is compatible with most USD-based headsets that use standard Windows USB driver.</p> <p>Softphone support for Jabra:</p> <ul style="list-style-type: none"> • Jabra Evolve 30 (Mono 7 Stereo) • Jabra Evolve 65 Stereo UC& Link 370 • Jabra Engage 75 • Jabra Engage 65 <p>Note: Mitel does NOT support Bluetooth headsets that connect directly to the PC's Bluetooth port. The user experience with Bluetooth has been proven to be</p>

	<p>disappointing in office environments due to interference from Corporate WiFi.</p> <p>The softphone is compatible with Bluetooth headsets that connect to a USB base in the PC.</p>
Microsoft Office	<ul style="list-style-type: none"> • Microsoft Exchange Server 2013 and 2016, 2019 • Microsoft Office 2013, 2016 and Office 365
Mitel IM Server	<ul style="list-style-type: none"> • SA-100: 22.22.6100.0 • SA-400: 22.22.6100.0
SIP-BRI-8	<ul style="list-style-type: none"> • Version R3.T 2006-10-04 • T.38 is not supported
Mitel Connect Contact Center	<ul style="list-style-type: none"> • 507.85.3221.0 and greater
Mitel Connect Mobility	<ul style="list-style-type: none"> • Mitel Mobility Router 9.5.1809.105 (MMR) and greater • MMR Appliances: MR2000, MR4000, and MR6000
Ingate SIParator	<ul style="list-style-type: none"> • Hardware SIParator (firmware version 5.0.6) • Software SIParator (version 5.0.6) X86 or VMware • 6900 Teleworker Requires SIParator software version 6.4 or greater
VPN Concentrator	<ul style="list-style-type: none"> • VPN Concentrator 4500, FW 11.6.1.7 • VPN Concentrator 5300LF, FW 11.6.1.7 • VPN Concentrator 4550, FW 13.12.6.2 • VPN Concentrator 5300 LF2, FW 13.12.6.2 • VPN Concentrator 7301, FW 13.12.6.2
Mitel Connect Telephony for Microsoft	<ul style="list-style-type: none"> • Lync Plugin 214.100.3131.0
Mitel Connect Hybrid (Fax & Scribe)	<ul style="list-style-type: none"> • Mitel Connect Scribe • Mitel Connect Fax
Multi-cell DECT Phones (Firmware: 4.40 B3) [EU Only]	<ul style="list-style-type: none"> • Phone Models: 8430, 8630 and 8830 • Base: 8860 • Repeater: V41
Mitel SIP-DECT	<ul style="list-style-type: none"> • Phone Models: 612d, 622d and 632d • Base Stations: RFP44,45,47,48 • Version: 8.3.SP1
Mitel Edge Gateway	<ul style="list-style-type: none"> • See VMware and Hyper-V
Mitel Service Appliance	<ul style="list-style-type: none"> • SA-100: 22.22.6100.0 • SA-400: 22.22.6100.0

Mitel Network Helper	<ul style="list-style-type: none">• 0.0.62
----------------------	--

Accessing the Latest version of MiVoice Connect Software

All MiVoice Connect releases can be found in Mitel Access Website. Follow the steps below to download the latest version of MiVoice Connect 19.3:

1. Log in to Mitel [MiAccess](#)
2. Click on the **Software Download Center** in the leftmost pane
3. You can *search by name* or *Navigate by Categories* and find the **MiVoice Connect** category
4. Select the appropriate version and follow instructions on the software download Page

Documentation

The documentation mentioned below can be found [Here](#), in the Mitel Document Center.

- Mitel MiVoice Connect Migration Guide
- Mitel MiVoice Connect System Administration Guide
- Mitel MiVoice Connect Planning and Installation Guide
- Mitel MiVoice Connect Maintenance Guide
- Mitel MiVoice Connect Release Build Notice
- Administration Guide for Connect Edge Gateway
- Connect Client User Guide
- Mitel Virtual Mobility Router Installation Guide
- Mitel MiVoice Connect Contact Center Installation Guide
- RAY BAUM'S General Overview and Solution Deployment Guide
- RAY BAUM'S General Overview and Solution Deployment Guide for RedSky
- RAY BAUM'S General Overview and Solution Deployment Guide for Intrado
- MiVoice Connect Ingate SIParator as Teleworker Gateway for MiVoice Connect 6900 Series Configuration Guide

The documentation mentioned below for the 6900 IP Series phones can be found [Here](#)

- 6900 SIP Phones and Accessories
- Mitel 6900 and IP400 Series IP Phones for MiVoice Connect Functionality Differences

Training

[Mitel University Training](#)

[Learn Now](#)

Important Links

The MiVoice Connect Release Notes provide essential, current information to ensure a successful migration and installation. This includes supplemental information to the current Mitel documentation suite available on the Mitel support web site [MiVoice Connect \(Mitel.com\)](#).

Mitel product enhancements are submitted to [Mitel User Voice](#). The User Voice forum can be found in the MiAccess portal. Mitel uses your feedback to establish content for future releases.

Mitel MiVoice Connect software downloads are available via the Software Download Center. Mitel MiVoice Connect software download require [MiAccess login](#), as well as Export Control Disclaimer completion and submission.

Installation and Upgrade Notes

1. Microsoft Updates

Mitel tests MiVoice Connect with all available Microsoft security patches up to the release date of each MiVoice Connect software version. After installation, Mitel recommends that customers follow their own company's security guidelines for maintaining the Windows Server OS. If a phone system problem occurs, customers may be asked to roll back one or more security patches as a troubleshooting step if it appears to be related to the issue under investigation. To reduce potential impact, it may be advisable to apply only critical and high importance updates.

Note: Mitel strongly advises customers to back up their MiVoice Connect system before opting for any Microsoft updates. Please refer to the [Mitel Connect System Administration Guide](#) for backup instructions.

This build was tested with all available and automatically installed Microsoft Windows Server updates (important and recommended) as published on or before **June 25, 2022**. If you are an existing MiVoice Connect customer, please review the table below to find whether you can install the tested Microsoft updates on your server without upgrading the entire Connect system.

Release Notes

Release	Build	Build Test Date
Release 19.3	22.22.6100.0	June 26, 2022
Release 19.2 – SP3	22.20.2300.0	Dec 15, 2021
Release 19.2 – SP2	22.20.1300.0	Nov 08, 2021
Release 19.2 – SP1	22.18.4600.0	June 14/Aug 31, 2021
Release 19.2	22.13.4800.0	November 6, 2020
Release 19.1 – SP2	22.11.9300.0	April 4, 2020
Release 19.1 – SP1	22.11.4900.0	February 1, 2020
Release 19.1	22.10.7600.0	September 20, 2019
R1807 – Onsite – SP2	21.90.9743.0	June 18, 2019
R1807 – Onsite – SP1	21.90.9738.0	January 27, 2019
R1807 – Onsite	21.90.4127.0	October 12, 2018
R1804 – Onsite – SP1	21.88.3753.0	September 6, 2018
R1804 – Onsite	21.88.3731.0	June 27, 2018
R1803 – Onsite	21.87.9727.0	May 5, 2018
R1801 – Onsite*	21.87.3629.0	March 20, 2018
R1711 – Onsite	21.86.1828.0	January 16, 2018
R1707 – Onsite – SP2	21.84.5543.0	November 28, 2017
R1707 – Onsite – SP1	21.84.5535.0	October 18, 2017
R1707 – Onsite	21.84.5523.0	August 29, 2017
R1704 – Onsite – SP2	21.82.9645.0	July 28, 2017
R1704 – Onsite – SP1	21.82.9630.0	June 13, 2017
R1704 – Onsite	21.82.9623.0	June 2, 2017

- *Ensure [KB2919355](#) is installed on Windows Server 2012 R2 prior to loading the PBX software

2. R1801 and Greater - Windows Server 2016 Installer Prerequisites ISS Version Support

Note: Scripts are available to address the issue that 2016 Server ships with IIS 10 and these PBX prerequisites fail to recognize it as a higher version than IIS 7.0.


- Review *Read_first_for_2016.txt* and, if necessary, run the following:
- *SetIIS_version.vbs*, and *ResetIIS_version.vbs*, in *MiVC_Connect_PBX_Build* zip, 2016 Scripts\ folder)

3. Starting with R1711 (21.86.1828.0) Features & Changes

- Linux WindRiver to Linux CentOS Migration – This is a mandatory migration and configuration changes are required to the SCSI Controller before or during the upgrade to this build. It is highly recommended to review the SCSI Change Controller video before upgrading virtual appliances to this build. These changes impact:
 - Virtual switch (IP Phone to SIP Trunk)
 - Virtual Service Appliance (Collaboration)
 - Service Appliance (Collaboration) SA-100 and SA-400
 - Linux DVS
 - Packaging Changes:
 - There will be no standalone installer for Linux DVS. Linux DVS software will be integrated into HQ and Staging Firmware installers; this will streamline the installation process.
 - Virtual appliances (Switches, Linux DVS, and Service Appliance (Collaboration)) will use .iso instead of .ova packaging.
 - Administrators are encouraged to follow the updated references for virtual appliances installation, upgrades and backup/recovery:
 - [Mitel Connect Migration Notes](#)
 - [Planning and Installation Guide Installation Guide](#)
4. Mitel ST Switches - Dual stage upgrade is not an option on the first migration to MiVoice Connect
 5. Mitel IP Phones - Automatic phone firmware upgrades are on by default. System administrators will need to disable this feature from Director if manual upgrade of IP Phones is desired.
 6. Disable the IP Phone Failover
 - Disable the IP Phone Failover feature in Director when upgrading from ST13/ST13.x/ST14/ST14.x; otherwise, a failover condition will be induced upon the upgrade. The fallback is not automatic. It is a manual process to move the users back to their primary switch and not the spare switch.
 - Steps to temporarily disable IP Phone Failover across Sites
 - 1) Log into Director
 - 2) Go to Quick Look page
 - 3) Ensure the checkbox is checked "Temporarily Disable IP Phone Failover Across Sites"
 7. Migration Paths -The following direct **server upgrade paths** are supported for this release:
 - **NOTE: Direct Upgrades from ShoreTel releases prior to ST14.2 are not supported**
 - **Sites running ST14.2 GA30 MUST Migrate to 19.1 SP2 prior installing MiVoice Connect 19.2.**


- Please study the updated **14.2-to-Connect Migration Guide** for more details.

➔ Older ST 14.2 versions require HQ and DVS Upgrade to **latest 14.2 GA30** - 19.50.1000.0




➔ ST14.2 GA30 requires System Upgrade to **MiVC 19.1-SP2**

- Endpoints do not require this intermediate step
- Voice Switches do not require this intermediate step



➔ Any existing MiVoice Connect or Connect ONSITE can upgrade directly to 19.2 or **19.2 SP3**



Direct MiVoice Connect migrations from versions prior to those listed above are not supported. Prior versions must first upgrade to a supported direct migration path.

In addition,

➔ Mobility versions 7 or 8 must upgrade Mobility version 9:



➔ Contact Center 8 or 9 must upgrade to Connect Contact Center:



Migration from Windows Server 2008 (32 bit) or earlier to a supported Windows Server OS version must be done prior to migrating to MiVoice Connect.

8. The UC20 Windows server is not supported with MiVoice Connect. For more information, please refer to the Mitel Connect Migration Notes that can be found [here](#):

NOTE: Some systems were upgraded to Connect from earlier versions of 14.2 and did not perform an interim upgrade to 14.2 GA30. Admins may find these fail a Connect-to-Connect upgrade directly

to 19.2 or higher, and the installation rolls back unexpectedly. Performing an intermediate upgrade stop at 19.1 SP2 *before* moving to 19.2 or higher has been proven to resolve the issue and allow the upgrade to complete. After the stop at 19.1 SP2 customers can continue to 19.2 or higher without incident.

Mitel 6900 Phone Upgrades from 19.2 GA or older

When upgrading the Mitel 6900-series phones to phone firmware 6.0 or greater which was first released with 19.3, some phones may fail to upgrade. The problem occurs because temporary log files are not cleared before downloading the new firmware, which can cause insufficient internal working storage for the update.

To prevent this problem, Mitel recommends upgrading all 6900-series phones to updated firmware build version [5.2.1.2130](#) before the system upgrade to 19.3. Administrators may also choose to manually reboot the phones then promptly upgrade to the new 19.3 firmware before the log files accumulate. In some cases, multiple phone reboots have been required.

DHCP Scope Considerations for 6900 Phone Series

MiVoice Connect 19.3 requires the DHCP scope changes announced in Release 19.2. In releases of MiVoice Connect before 19.2, the recommended guidance for DHCP option 156 was to configure the “Config Server” parameter with IP address of HQ Server. In Release 19.2 and onward, an FQDN is now required in the DHCP record if Subject Alternate Name (SAN) is root Certified. In cases where DHCP Scope 156 is not used, administrators must update the config server setting on 6900 sets manually, from IP to FQDN. If the IP address is used, users may encounter 6900 registration or boot issues after the upgrade to 19.3 or later.

- NTP Server settings must also be specified in Option 42 of the DHCP scope for 6900 phones to validate certificate expiration dates. For more information, see the *MiVoice Connect Maintenance Guide*.

Resolved Issues

The List below contains MiVoice Connect 19.3 and latest Phone 6900 Firmware resolved issues:

Issue Key	Resolved in MiVC 19.3
MIVC-4152	Updates to the <i>Mitel for Zendesk Deployment Guide</i> . Links to Zendesk resources have been updated
MIVC-4018	Cannot join web conference audio via computer/audio option from Chrome or Edge browsers
MIVC-4007	Jack Based Music On hold option is missing from Director for SGT1K switch type.
MIVC-3938	Cannot change trunk group when HQ is configured as SMDI Voicemail server
MIVC-3687	While Listening to Workgroup Voicemail, if Interrupted by a voice call a user cannot listen to the message again afterwards if they attempt to.
MIVC-3658	Digit translation table cannot have more than 99 working entries

Issue Key	Resolved in MiVC 19.3
MIVC-3618	Updates to the <i>MiVoice Connect RAY BAUM'S General Overview and Solution Deployment Guide for Red Sky</i> . Red Sky Configuration parameters have been updated.
MIVC-3530	Emergency 911 calls are handled normally when a 9100 range is present.
MIVC-3418	HeapStatus DB tables causing Sysmgr to crash after an upgrade or new DVS installation.
MIVC-3358	Calls to Auto Attendant Fail to load configured Voice Prompts Periodically
MIVC-3357	<i>Find Me</i> Feature calls are disconnected and sent to voicemail instead of the External destination
MIVC-3346	Some Connect PBX service start and stop events are not displayed in Director Event Logs
MIVC-3286	Advanced Reporting Application Fails to install on Windows 2019 Server
MIVC-3248	Mobility - Emoji not visible on mobile client
MIVC-3247	Mobility: Client shows custom presence text if user is in available status
MIVC-3243	IPDS crash when moving Switches between HQ and DVS server and vice versa
MIVC-3186	Security vulnerability in Apache Log4j library as CVE-2021-44228
MIVC-3175	Salesforce Softphone plugin: does not activate on current browser tab if opened previously on another tab
MIVC-3104	Periodic connection issues to RAST service due to Edge Gateway core dump
MIVC-3060	SysMgr service fails to start after upgrade if disk reclaim tool was run prior
MIVC-3044	Analog phones hear ringback tone on active calls
MIVC-3031	Mobility Router ICMP time stamp response vulnerability (CVE-1999-0524)
MIVC-2932	Cannot activate new system License Key after migration to new server
MIVC-2897	Mobility Router: Anonymous SSL cipher security vulnerability (CVE-2007-1858)
MIVC-2742	Mobility Router: Unable to start SIP service when uploading wild card certificate into the Local certificate
MIVC-2674	Connect Client Log4Net.dll security vulnerability (CVE-2018-1285)

Issue Key	Resolved in MiVC 19.3
MIVC-2643	Unable to retrieve parked calls if phone user is managed by the LDVS
MIVC-2474	Cannot upload the Record2File2 files when SG/ST series switch is managed by LDVS
MIVC-2472	Director Route Points description update in the User interface
MIVC-2371	CDR migration errors after Upgrades to 19.2 SP1
MIVC-2358	Security Vulnerability: Nginx library Updates for PBX
MIVC-2159	Mobility Client: unable to search Enterprise directory “cannot connect to server”
MIVC-2138	High I/O usage caused by CDR processing
MIVC-1942	ST100DA-E1 port programming from director configures the next port up. Example: configure Port 1 and Port 2 is configured.
MIVC-1774	Unable to provision/configure Mobility Router on R2012 server or later
MIVC-1731	During Failover, Spare switch shows Firmware Update Available instead of In-service
MIVC-1380	Cannot pause Recording in salesforce integrated client
MIVC-1266	Cannot dial internal extensions with Site Prefixes
MIVC-1176	Mobility Router responding to ARP requests from IP addresses that are not configured.
MIVC-2464	The Connect Client creates a Debug.log file on the user desktop
MI-50	IP400 NTP client crash when connection lost to external NTP server
MI-121	Incoming calls are auto answered during Revolution Bell or announcement
MI-65	IP400 periodically reboots due to a Kernel unhandled exception

Known Issues

Defect	Description	Workaround
PBX		
ENG-555434	Message waiting indicator not blinking consistently with Cortelco analog phones on the ST48A switch	Mitel will resolve this issue in a future release
MIVC-3942	CAS and TMS Service Start failures on Dell 15th Generation Servers. For more information please review the info channel services alert here	Mitel will resolve this issue in a future release
6900 Series Phones		
DTP-50863	6970 Conference Phone, Packet Fragmentation on calls	By Default, 'All' codecs are advertised on the 6970 which can cause packet fragmentation on some networks. Workaround: go into the Web UI of the 6970 and update the Codec list from "all" to the proper supported Codecs in use for the Connect deployment.
Connect Client		
MIVC-2882	When attempting to set Location in Connect client for RAY BAUM'S compliance the form does not render properly. You cannot set the Location	Mitel will resolve this issue in a future release

	<p>successfully when the menu renders this way.</p> <p>To work around this, close and re-open the Emergency Location menu and the form to set your location will render properly.</p>	
MIVC-2973	<p>Connect Client users with fixed Device (not softphone) will see Red Exclamation in CTI Mode.</p> <p>This display status only applies to a softphone Configured and can be ignored in CTI mode.</p>	Mitel will resolve this issue in a future release
MIVC-4215	<p>Connect Client: Exchange Credentials are required for Outlook UCB add-on. This feature does not work with PBX authentication</p>	Mitel will resolve this issue in a future release
MIVC-4145	<p>Connect Client: Single sign on required for Outlook Contacts plugin. This feature does not work with PBX authentication</p>	Mitel will resolve this issue in a future release

Known Product Limitations

Product Limitation	Description
Windows Server Secure Driver Signing	<p>During Installation of MiVoice Connect you receive a message “A digitally signed driver is required for Shoreware media Driver”, blocking installation.</p> <p>The workaround is to disable secure boot in the bios preventing the digital signing verification from occurring.</p> <p>Mitel is working to resolve this in a future release.</p>
VMware	<p>Review Mitel Application Note AN10391 “Deploying MiVoice Connect with VMware”. The VMware deployment requires careful planning using those references. One important consideration is a dedicated NIC especially for sites with voice quality issues.</p>
VMware	<p>Disaster Recovery is not supported on servers running on VMware. Customers should leverage VMware failover options such as HA.</p>

Product Limitation	Description
VMware	HA failover option only supported for HQ server not for DVS. In addition, no failback is needed since the VM gets moved to a new host in case of HA failover for HQ.
VMware	Fault Tolerance feature is not supported
SA100/400	Call Me feature not working over SIP Tie Trunk
SA100/400	By default, the SA100/400 belongs to a User Group called Audio Conference. Any restrictions on calling need to be configured in this User Group or the SA100/400 needs to be assigned to a different User Group.
SA100/400	Federation of instant conferences between systems is not supported
SA100/400	Outlook calendar Integration for SA100/400 is not supported in a configuration in which one user is a delegate for another user and the user tries to create a SA100/400 conference on behalf of another user. The same is true of calendar sharing.
SA100/400	For a recurring Outlook appointment containing a SA100/400 conference, it is not possible to modify the properties of a single occurrence of the conference and have the modification apply to just that one occurrence; the modification ends up applying to all occurrences of the conference.
SA100/400	Disaster Recovery not yet supported
SA100/400	Partitioning not yet supported
SA100/400	Linux Security Patch utility not yet supported
Certificates	Certificates are a key part of the improvements to the security architecture for Connect. If the certificates are not installed properly it may adversely impact depending on your customer's needs, Certificates may need to be ordered in advance of the migration. Review the Certificate procedures in Mitel's Technical documentation and listen to Webinars (found by searching on Certificates and Tech Talks)
Mitel ST switches	Dual stage upgrade is not an option on the initial migration from ST14.2 to Mitel Connect
Mitel IP Phones	Automatic phone firmware upgrade is on by default. System administrators will need to disable this feature from Director if manual upgrade of IP Phones is desired.
ST Switches	<p>Serial login: Difference from Legacy Switches the Baud rate has increased from 19200 to 115200.</p> <p>SSH Login: Difference from Legacy Switches ST voice switches are only accessible with the HQ_RSA key (Use Puttygen to create *.ppk key)</p> <p>Difference from Legacy Switches ST voice switches do not allow telnet access</p>

Document Revisions:

Date	Description	Version
29 June-22	19.3 First publication	1.0