## **RESOLVED ISSUES in Mitel Connect Mobility Router**

This article contains resolved issues for Mitel Connect ONSITE Mobility Router Releases. For Client resolved issues refer to bug fixes in the application description App Store for iOS and Android.

| Known issues fixed in Mitel Connect Mobility build CMR 9.6.2011.102 |  |
|---|--|
| Defect Number   | Description  |
| ENG-583543  | System failure on sy2smrs01pev: Process failure: sip_server  |
| ENG-583210  | Router - In Configuration/Voice/Advanced/Voice Prompt Profiles, "Change File" button of Profile Details table should disable if selecting many Profiles. |
| ENG-583395  | Router - In Configuration /System /Authentication /Directory, should correct UI and functions  |
| ENG-583380  | Router - In Configuration/Voice/IP PBX, the Numbering Plan tab should work correctly.  |

| Known issues fixed in Mitel Connect Mobility build CMR 9.6.2008.105 |   |
|---|---|
| Defect Number   | Description   |
| ENG-581729  | DECT phone to Mobility - No audio   |
| ENG-581746  | Router - CCD's one-way audio after complete consult transferring when G722 is configured as a lower priority in CMR but a top priority for PBX. |
| ENG-582278  | Router - Should show G.722 code in Mobility Router Preferred Code List when adding new IP PBX   |

| Known issues fixed in Mitel Connect Mobility build CMR 9.6.2004.104 |  |
|---|--|
| Defect Number   | Description  |
| ENG-579753  | CMC - Router - The G.722 codec disappeared when pressing "Default " button in setting        |
| ENG-580592  | Router - No way audio after hand-out when G.722 is configured as top codec on CMR and PBX.   |
| ENG-579740  | CMC - Client - Automatic drop call when move call between CMC and deskphone after 30seconds. |

| Known issues fixed in Mitel Connect Mobility build CMR 9.5.1910.102 |  |
|---|--|
| Defect Number   | Description  |
| ENG-576192  | CMR – R1906-CMC is not able to register after upgrading CMR to 9.6.0.177             |
| ENG-572056  | Presence Login failure happens with "Invalid URL! url=https://:5448/Login" error     |
| ENG-575741  | CMC – Client-Both CMC and desk phone ring when moving call if user is in onhold call |

| Known issues fixed in Mitel Connect Mobility build CMR 9.5.1907.103 |   |
|---|---|
| Defect Number   | Description   |
| ENG-575870  | 9.5.1904.102 image on VM is giving errors while adding Mitel Directory and Groups on a fresh install                        |
| ENG-576925  | CMR - Numbering Plan Templates are empty and End User Licenses are zero when deploying the OVA file with build 9.5.1907.101 |
| ENG-574669  | CMR (Push build) - Cannot modify IP PBXs on CMR portal  |
| ENG-575048  | CMR - Server has crash logs when users search enterprise contact  |
| ENG-568360  | CAS_Server module crash happened in the CMR.  |

| Known issues fixed in Mitel Connect Mobility build CMR 9.5.1905.106 |  |
|---|--|
| Defect Number   | Description  |
| ENG-575870  | 9.5.1904.102 image on VM is giving errors while adding Mitel Directory and Groups on a fresh install |
| ENG-561082  | iLBC Codec mismatch from incoming calls to CMR   |
| ENG-574669  | CMR (Push build) - Cannot modify IP PBXs on CMR portal   |
| ENG-563461  | CMR Vulnerability alert – does not support AEAD cipher suites  |
| ENG-571474  | CMR Sending INVITES to Mobility Clients of change of RTP port every 10 seconds                       |
| ENG-561771  | CMR-VQD- There are no VQD statistics displayed on the Call quality tab on D2 for mobility calls      |
| ENG-547072  | CMC- Call is not forwarded to Voicemail when CMC is on cellular access                               |

| Known issues fixed in Mitel Connect Mobility build CMR 9.5.1810.110 |  |
|---|--|
| Defect Number   | Description  |
| ENG-560485  | MT: No audio between CMC and softphone after the call is moved from softphone to CMC |
| ENG-561082  | iLBC Codec mismatch from incoming calls to CMR                                       |
| ENG-547072  | CMC- Call is not forwarded to Voicemail when CMC is on cellular access               |

| Known issues fixed in Mitel Connect Mobility build CMR 9.5.1809.105 |   |
|---|---|
| Defect Number   | Description   |
| ENG-558240  | CMC2 - CMR: After upgraded CMR, CMC can't make calls  |
| ENG-547072  | CMC- Call is not forwarded to Voicemail when CMC is on cellular access  |
| ENG-526551  | CMR: User password is logged in RAST logs   |
| ENG-535275  | CMC2 - Client - The call screen of parties in Adhoc conferecence still show user name who was enable "Make extension private" |

| Known issues fixed in Mitel Connect Mobility build CMR 9.5.1808.112 |  |
|---|--|
| Defect Number   | Description  |
| ENG-548725  | CMC2 - Client - Unable to escalate Video call after Cancel   |
| ENG-556740  | CMC2: VQD: There is just one PUBLISH SIP log on PBX  |
| ENG-556770  | Feature flag for VQD   |
| ENG-548526  | CMC2: VQD:MT: SipStack::OutOfDialogMsgRcvdEvHandler: incoming out of dialog PUBLISH request message in the log |
| ENG-556786  | CMR Vulnerability alert on TLS1.2  |
| ENG-548586  | CMC2 - Client - Can't merge call successfully  |
| ENG-548589  | CMC2 - Client - Can't consult transfer successfully  |

| Known issues fixed in Mitel Connect Mobility build CMR 9.5.1807.105 |  |
|---|--|
| Defect Number   | Description  |
| ENG-548725  | CMC2 - Client - Unable to escalate Video call after Cancel   |
| ENG-556740  | CMC2: VQD: There is just one PUBLISH SIP log on PBX  |
| ENG-556770  | Feature flag for VQD   |
| ENG-548526  | CMC2: VQD:MT: SipStack::OutOfDialogMsgRcvdEvHandler: incoming out of dialog PUBLISH request message in the log |

| Known issues fixed in Mitel Connect Mobility build CMR 9.5.1806.105 |   |
|---|---|
| Defect Number   | Description   |
| ENG-541362  | CMR > Configuration> Users page "Enterprise Full Number" is not displayed completely for few global users         |
| ENG-545760  | Call drops when try to perform Blind transfer using DID   |
| ENG-547068  | AUS-Directory search is not working from CMC  |
| ENG-542541  | Voicemail Access Number is coming as blank for Global Users group created   |
| ENG-545840  | Cannot Dial locally and International without using Trunk Access Code(9) for Ireland and Switzerland global user. |
| ENG-547066  | AUS- Enhanced Mobility/Simulring not working for CMC while dialing DID  |
| ENG-547071  | AUS- Call is not coming to cell when CMC is on cellular access  |
| ENG-542522  | Caller ID is not right while dialing from UK to US number   |

| Known issues fixed in Mitel Connect Mobility build CMR 9.5.1804.115 |   |
|---|---|
| Defect Number   | Description   |
| ENG-537876  | The Video call from CMC to CMC does not work in Mobility system.  |
| ENG-535262  | [Microsoft Hypervisor 2016 on Hyper-V] - Fresh install of CMR with ISO deployment on Hypervisor set up fails with network interfaces not getting created. |
| ENG-526583  | Unable to perform CAS functionality from Mobility Clients (CHM/VVM) on Connect Cloud Mobility Clients.  |
| ENG-535370  | "RAST_Server" Process failed, causing the CMR switchover.   |
| ENG-526551  | User password is logged in CMR RAST log.  |

| Defect Number | Description   |
|---------------|---|
| ENG-526134    | CMR SSL engine initialization always initializes with TLS 1.1, and hence, results in handshake failure with PBX, causing User registration failure. |
| ENG-524361    | Mobility Client User logged-in with Remote Wi-Fi/Cell data; but, cannot register to CMR.  |
| ENG-526120    | CMR configuration should allow for support for min TLS version 1.0.   |
| ENG-505689    | Issue with Music on Hold when holding Conference using SA-100.  |
| ENG-522543    | SSL Security Vulnerabilities with CMR.  |
| ENG-522511    | CMR UI for selection of min TLS configuration.  |
| ENG-496852    | Presence Login (and hence, Location change) fails in CMC (both on Android & iPhone)   |
| ENG-494981    | SSL/TLS Server supports TLSv1.0 in CMR 8.1.10.106, causing security vulnerability.  |
| ENG-481380    | Current Active Video Call Duration not include duration of HOLD state in the CMR Admin UI.  |
| ENG-496107    | Buddy/group list is NOT updated after added/removed on Android 7.x  |
| ENG-492813    | CMR Username limited to 31 Characters.  |
| ENG-515092    | When the call is ended from Called Party, the connection between CMC and CMR failed, and also, "SIP_Server" module crashed.                         |
| ENG-515641    | CMR Mitel Rebranding.   |
| ENG-499685    | Mitel Connect for Mobile Client should add Favorites successfully.  |
| ENG-498976    | Mitel Connect for Mobile Client should delete Favorites successfully.   |

| Known issues fixed in Mitel Connect Mobility build CMR 9.1.11.107 |   |
|---|---|
| Defect Number   | Description                                 |
| ENG-512056  | To remove the license restrictions for CMR. |

| Known issues fixed in Mitel Connect Mobility build CMR 9.1.9.106 |  |
|--|--|
| Defect Number  | Description  |
| ENG-494421   | Line Registration failure.   |
| ENG-497998   | SIP Server module crashes multiple times on Mitel Connect Cloud System.  |
| ENG-437425   | CAS module did not work at first and after 3 crashes, it started to work in the Mitel Connect Mobility system. |
| ENG-492736   | User is unable to complete extension dials from the CMC, as CMR is getting 403 Forbidden from PBX switch       |
| ENG-493793   | When CMR calls CMC on Cellular Network, Called ID sometimes does not display correctly.                        |
| ENG-482487   | Mobility App (CMC) shows wrong time for Instant Messages.  |

| Known issues fixed in Mitel Connect Mobility build CMR 9.1.8.106 |  |
|--|--|
| Defect Number  | Description  |
| ENG-481312   | Mobility Users Receive 403 Forbidden Message - Call Failure Network Busy   |
| ENG-479473   | VMware Tools not running on ESXI-6 for build 9.0.87.105  |
| ENG-381488   | "Server Error Occurred" message pops up repeatedly on Physical CMR, MR4000.  |
| ENG-481296   | CMR should not have the following rule: X*-> +(LCC)(LAC)X*   |
| ENG-493793   | [US40763: CMR: Mobility Caller ID Enhancement] Whenever, a PBX user (Deskphone extension) makes a call to Mobility User, and the call is received by the Mobility user in cellular network, the call never used to show the caller ID of the caller. |

| Known issues fixed in Mitel Connect Mobility build CMR 9.1.4.107 |   |
|--|---|
| Defect Number  | Description   |
| ENG-482610   | CMR is not sending the Caller ID in E164 format in "From" header  |
| ENG-481211   | Caller ID is not displayed correctly when extension to extension call is placed.                            |
| ENG-477464   | Audio is garbled when call is routed to Auto Attendant and low bandwidth codec (iLBC) is selected.          |
| ENG-461798   | Security issues with Mobility 9 (Connect) for OpenSSL Padding/OpenSSL 1.0.2h                                |
| ENG-024613   | Mobility to Desk Phone call for iLBC to PCMU Codec is failed when RTP Bridging is ON and Transcoding is ON. |

| Known issues fixed in Mitel Connect Mobility build CMR 9.0.87.105 |   |
|---|---|
| Defect Number   | Description   |
| ENG-441025  | CMR- Need to support importing 3rd party certs before creating local CA self-signed certs |

| Known issues fixed in Mitel Connect Mobility build CMR 9.0.86.103 |  |
|---|--|
| Defect Number   | Description  |
| ENG-432006  | Can NOT CSR Key with wildcard (*) in Common Name field, as CMR Portal does NOT accept asterisk character |
| ENG-437397  | CMR Server outage  |
| ENG-441058  | CMC-Android- Order in which IM's are received is not correct.  |

| Known issues fixed in Mitel Connect Mobility build CMR 9.0.84.104 |                   |
|---|-------------------|
| Defect Number   | Description       |
| ENG-423801  | CMR Server outage |

| Known issues fixed in Mitel Connect Mobility build CMR 9.0.82.119 |   |
|---|---|
| Defect Number   | Description   |
| ENG-328433  | Compliance vulnerability scan on external facing IP's for the Mitel Mobility Router |
| ENG-387240  |   |
|   | Can NOT add more than 1000 users on CMR system                                      |
| ENG-387280  | Mitel Connect (ONSITE) Mobility does NOT support wildcard certificate               |